

objekt	typ	vonkajši	vonkajšie	vnútorné	vnútorné	poznámky	náplň
<b>Bytový dom Michalovce</b>		<b>5</b>		<b>5</b>			
4 byty	LG	1	S 12 AHP	1	S 12 AHP	14.7.2010	R410A/0,93 kg
	LG	1	S 12 AHP	1	S 12 AHP	14.7.2010	R410A/0,93 kg
	LG	1	S 12 AHP	1	S 12 AHP	14.7.2010	R410A/0,93 kg
	LG	1	S 12 AHP	1	S 12 AHP	14.7.2010	R410A/0,93 kg
Marek Eštok - byt	Samsung	1	AQ12FAN	1	AQ12FAN		R410A/0,92 kg
<b>administratívna budova</b>		<b>15</b>		<b>15</b>			
vedúci	Midea	1	MSB 12 HRN2	1	MSB 12 HRN2		R407C/0,86 kg
sekretariát	Mitsubishi	1	MSC-09RV	1	MSC-09RV		R22/0,85 kg
strážna služba - HRM	Mitsubishi	1	MS-GA50VB	1	MS-GA50VB		R410A1,45 kg
strážna služba - HRS	Mitsubishi	1	MS-GA60VB	1	MS-GA60VB		R410A/2 kg
ing. Zalom	Samsung	1	AQ 09FAN	1	AQ 09FAN		R410A/0,92 kg
Kundrátová	Plasma	1	Plasma SR-09H	1	Plasma SR-09H		R410A/0,92 kg
ruska kancelária	LG	1	S 09 AHP	1	S 09 AHP	20.8.2010	R410A/0,93kg
ukraj.kancelária	LG	1	P09RL	1	P09RL	9.7.2014	R407C/0,90 kg
laboratórium	Tekno Point	1	SP2-21H	1	SP2-21H		R407C/0,75 kg+1
labor. - kancelária	Plasma	1	Plasma SR-09H	1	Plasma SR-09H		R410A/0,92 kg
laboratórium	Ionizer	1	SP2-21H	1	SP2-21H		R407C/0,58 kg
labor. - mobilna klim.	Midea		MPA-09ERM2		MPA-09ERM2		R407C/0,58 kg
technolog.miestnosť RR	Daikin	1	RXS60L/RXS60L2V1B	1	FTXS60G/FTXS60GV1B	2016	R-410A/1,5kg
RR	Daikin	1	RXS60F	1	FTXS60G	2013	R410A/1,5 kg
ruska kancelária	Midea	1	MSG-12CRM2	1	MSG-12CRM2		R407C/0,83 kg
vrátnica	Mitsubishi	1	MS-GA50VB	1	MS-GA50VB		R410A/1,45 kg
<b>sklady a dielne objekt 080 100</b>		<b>11</b>		<b>11</b>			
bufet	Midea	1	MSB-24HRN2	1	MSB-24HRN2		R407C/2,22 kg
bufet	Midea	1	MSB-24HRN2	1	MSB-24HRN2		R407C/2,0 kg
bufet	Midea	1	MSB-12CRN2	1	MSB-12CRN2		R407C/0,83 kg
kancelária p.Tomková	Midea	1	MSB-12HRN2	1	MSB-12HRN2		R407C/0,83 kg
zasad. miestnosť	Midea	1	MSR-12CRN2	1	MSR-12CRN2		R407C/0,83 kg
zasad. miestnosť	Midea	1	MSR-12CRN2	1	MSR-12CRN2		R407C/0,83 kg
dielňa elektroúdržba	LG	1	P 18 RK	1	P 18 RK	27.8.2013	R410A/1,35 kg

ing. Peňák, elektr. údržba	LG	1	P 09 RK	1	P 09 RK	27.8.2013	R410A/0,9 kg
dielne údržby TEZ	LG	1	S24EQ.U24	1	S24EQ.NSK	2019	R32 1,1 kg/0,74 kg
dielne údržby TEZ	LG	1	S24EQ.U24	1	S24EQ.NSK	2019	R32 1,1 kg/0,74 kg
dielne údržby TEZ	LG	1	S24EQ.U24	1	S24EQ.NSK	2019	R32 1,1 kg/0,74 kg
<b>starý PÚ</b>		<b>4</b>		<b>4</b>			
ing. Šimko	LG	1	PC12SQ.UA3	1	PC12SQ.NSJ	2019	R32 0,7 kg/0,47 kg
Mikloš	Plasma	1	SR-09H	1	SR-09H		R410A/0,92 kg
Révesz	Plasma	1	SR-09H	1	SR-09H		R410A/0,892 kg
Ing. Eštok	Midea	1	MSG-09HRN2	1	MSG-09HRN2		R407C/0,80 kg
<b>objekt 065</b>		<b>8</b>		<b>8</b>			
ing. Mištanič	Tekno Point	1	SRI-12H	1	SRI-12H		R410A/1,08 kg
serverovňa - kamer. Systém	Daikin	1	RXS60F	1	FTXS60G		R410/1,5 kg
serverovňa - kamer. Systém	Daikin	1	RXS60F	1	FTXS60G		R410/1,5 kg
Ing. Uhrín	York	0		0	Nefunkčná		R22/0,91 kg
velin smenový majster	York	1	MOC-09S15	1			R22/0,91 kg
velin	York	1		1			
Mazúr	Midea	1	MSG-09HRN2	1	MSG-09HRN2		R407C/0,85 kg
rozvodňa NN - dole	Daikin	1	FTYN50FV1B	1	FTYN50FV1B		R410A/1,5 kg
Ing. Čigaš	Midea	1	MSB-09HRN2	1	MSB-09HRN2		R407C/0,85 kg
<b>objekt stará MSR</b>		<b>1</b>		<b>1</b>			
meranie objemu ropy	Midea	1	MSG-09HRIN2	1	MSG-09HRIN2		R407C/0,85 kg
<b>Objekt PÚ</b>		<b>6</b>		<b>6</b>			
dispečing č. 1	Samsung	1	AQ24	1	AQ24		R410A/1,5 kg
denná miestnosť č. 2	LG	1	E12SQU	1	E12SQ	2011	R410A/0,90 kg
veliteľ ZHÚ č. 12	Midea	1	MSG-12HRN2	1	MSG-12HRN2		R407C/1,5 kg
učebňa	Tekno Point	1	SR-18H	1	SR-18H		R410A/1,77 kg
technici odb.služieb 22	Samsung	1	AQ09 FAN	1	AQ09 FAN		R410A/0,65 kg
veliteľ zásahu č. 14	Plasma	1	SR09H	1	SR09H		R410A/0,92 kg
<b>mobilna klimat.</b>	Midea		MPA-04ERM2		MPA-04ERM2		R407C/0,58 kg
<b>nová AB budova</b>		<b>3</b>		<b>13</b>			
kancelárie - kazetové KJ	Airwell	1	AQH 30	11		2013	R410A/ 7,6 Kg
	Daikin	1	RXS60F3V1B	1	FTXS 60	2013	R410A/1,5 kg

PS-1 Budkovce	Toshiba	1	RAV-SM806KRT	1	2015	R410A/2,1 kg
---------------	---------	---	--------------	---	------	--------------

<b>Spolu PS-1 + bytový dom</b>		<b>53</b>		<b>63</b>	<b>116</b>	
--------------------------------	--	-----------	--	-----------	------------	--



